



Belvac Production Machinery Technical Bulletin


Information for Customers Operating & Maintaining Belvac Machines

ISSUE 2, VOLUME 13, MARCH 2010


NECKER SYSTEMS ROTARY UNION REPLACEMENT

Belvac has used Duff-Norton brand rotary union (part number C48517) for many years on Autolube Necking systems. Due to quality issues with this unit that could not be resolved, Belvac partnered with Rotary Systems Inc. to develop a unique and robust rotary union specific to Belvac's application. A carbon steel construction with hardened shaft, dual seal ball bearings, and Teflon seals make the new rotary union distinctive and durable. The new rotary union is assigned a new Belvac part number C10179 that is directly interchangeable with the Duff-Norton unit for ease of maintenance and replacement in the field.

All new Belvac Autolube turrets, such as the Neckers, the Flangers, the Reformers/Re-profilers, and the Light Testers will use the new Rotary Systems union C10179 starting May 1st 2010. After this date, Belvac will no longer supply the Duff-Norton union C48517 on any of its equipments and will be automatically substituted with C10179. Should you have any questions, please contact our Service department at the numbers shown below and our friendly staff will be glad to help.



Discontinued Duff-Norton
Rotary Union: C48517



New Rotary Systems
Rotary Union: C10179